BUREAU OF PATROL

003rd District

27 January 2012

TO:

Christopher Fletcher

Commander 003rd District

FROM:

P.O. DeWayne Mason #13266

003RD DISTRICT

SUBJECT:

PDT Power Cable Damage

This TO/FROM subject report is being submitted by P.O. Mason #13266 due to the damage of PDT wiring. On this date upon vehicle inspection of vehicle #8461 at the start of tour R/O noticed the power wiring pulled from the PDT mounting bracket preventing the functioning of the PDT and disabling the GPS system. R/O took vehicle to Area 1 electrical maintenance for repair and PDT functioning resume. This same occurrence took place on 25 JAN 2012 for vehicle #8423 again PDT wiring was repaired. On one other occasion several weeks ago the same incident took place however R/O does not remember the vehicle or date.

P.O. D. Mason#1/3266

003RD District

Approved: